

## Revise History

Date	Version	Revision
2019/6/14	1.01.01.20R2	Bug fix: Long file names will no longer crash the system
2019/5/31	1.01.01.20R1	<ol style="list-style-type: none"> <li>1. Change the size of text in dual display mode.</li> <li>2. Added customer defined time base in the trend diagram.</li> <li>3. Enhanced the volume of buzzer.</li> <li>4. Bug fix: The screen saving setup was lost after power cycle/reboot.</li> <li>5. Moved CSV file save function from the utility page to the acquire page.</li> <li>6. Added recording measurement data to external U disk.</li> <li>7. Added the PT1000 temperature measurement.</li> <li>8. Bug Fix: when repeat single trig measurement, the screen is blocked.</li> <li>9. Optimize the temperature measure function.</li> </ol>
2018/10/29	1.01.01.20	<ol style="list-style-type: none"> <li>1. Add OCP function.</li> <li>2. Modify the calibration arithmetic of two wires resistance measurement.</li> </ol>
2017/4/14	1.01.01.19	<ol style="list-style-type: none"> <li>1. Add U disk recovery function.</li> <li>2. Modify Hold function arithmetic.</li> <li>3. Add the telnet SCPI function; port is 5024 Example: telnet 192.168.0.10 5024</li> <li>4. Repair the external trig problem.</li> </ol>
2016/3/17	1.01.01.16R2	<ol style="list-style-type: none"> <li>1. Improve the UI.</li> <li>2. Fix the bug in the trend chart.</li> <li>3. Modify the number of file systems from 2 to 3 and copy some configuration files to new location .This will reduce the chance of a system crash.</li> <li>4. Need to use transition software to update from old to new version.</li> </ol>
2015/10/29	1.01.01.15R2	<ol style="list-style-type: none"> <li>1. Fix the bug in thermocouple temperature measurement. Add a sufficient time delay to guarantee the validity of temperature ADC's reading.</li> <li>2. Modify the range of the product ID in update process check.</li> <li>3. Repair SCPI bug and RTD measurement bug.</li> </ol>
2015/9/22	1.01.01.15R1	<ol style="list-style-type: none"> <li>1. Speed up the refresh rate of UI.</li> <li>2. Modify the storage location of the product model and configuration files to upgrade.</li> <li>3. Add the diode threshold setting function.</li> <li>4. Fixed other miscellaneous problems.</li> </ol>
2015/4/01	1.01.01.12R1	<ol style="list-style-type: none"> <li>1. Fixed a problem where the LAN MASK setting cannot be saved after reboot.</li> </ol>

---

Date	Version	Revision
		2. Added Gateway setting.
		3. Fixed other miscellaneous problems.

---

## Update Instructions

1. If the firmware version in your SDM3055 is before 1.01.01.16R2 (not included), Please install the 1.01.01.16R2 firmware first.
2. You can find the firmware as below website:  
<https://siglentna.com/service-and-support/firmware-software/digital-multimeters/#sdm3055-series>