

## Revision History

Date	Version	Revision
2022/10/20	6.02.01.13	1. Compatible with new hardware
2021/7/30	6.02.01.11	1. Compatible with new hardware
2019/9/20	6.02.01.10R2	1. Optimize self-calibration for channels.
2017/4/7	6.02.01.08	<ol style="list-style-type: none"><li>1. Repaired bug causing Math error when trace is stopped in dot display mode</li><li>2. Fixed 'add measurement' error in Polish language</li><li>3. Bug repaired when measuring frequency of 500 Hz, using alternate trigger, and a time base of greater than 1 ms/div</li></ol>
2016/10/20	6.02.01.07	<ol style="list-style-type: none"><li>1. Fixed condition where wave trace departs from zero line while there is offset</li><li>2. Fixed condition where wave trace departs from zero line while there is offset</li><li>3. Fixed bug: All measurements on, select source on a disable channel. Reboot the Scope, then the software hangs on the boot screen</li><li>4. Adjusted keyboard scan method to optimize recognizing keyboard value</li><li>5. Modified BMP from 24bit to 16bit while save/get BMP form Scope</li><li>6. Fixed the bug: Wave trace disappear after STOP in scan mode</li></ol>
2016/5/10	6.02.01.02	The first formal release

## Compatibility between Versions

Source Version	Object Version	Compatibility
-------------------	-------------------	---------------

---

---

---

## Update instructions

Before updating the ADS file, the ADS file need to be renamed and ensured that its name contains less than 9 letters