

Revision Record

| Date | Version | Revision |
|------------|--------------|--|
| 3/29/2022 | 1.0.0.2.10 | 1. Added spectrum analyzer option |
| | | 2. Fixed input bug in network configuration window |
| | | 3. Fixed mouse click input box crash bug |
| | | 4. Increased the touch-sensitive area of the DHCP checkbox |
| | | 5. Modified the policy when the DHCP request fails |
| 12/29/2021 | 1.0.0.2.9.R5 | 1. Solved the menu button is not updated when the electronic |
| | | calibration module is inserted or removed |
| | | 2. Fixed a bug that the touch screen may crash under some |
| | | cases |
| | | 3. Fixed an option installation bug |
| 11/25/2021 | 1.0.0.2.9 | 1. Added some SCPI commands |
| | | 2. Solved memory leaks and crashed in some cases |
| 9/28/2021 | 1.0.0.2.8 | 1. Add shortcut buttons at the toolbar |
| | | 2. Fix the stuttering problem when adjusting the brightness of |
| | | the grid in the waveform area |
| | | 3. Solve the problem of probabilistic crashes when opening |
| | | dialogs |
| | | 4. File storage shortcut keys support more types |
| | | 5. Support more power meters |
| | | 6. Add picture editing function to the screenshot dialog |
| | | 7. Adds peak reference function for bandwidth search |
| | | 8. Modify the contents of the Chinese and English help files |
| | | 9. Modify the user receiver calibration process |
| | | 10. The input box will pop up automatically when using the |
| | | toolbar button to add Marker |