

Revise History

Date	Version	Revision
2017/4/14	1.01.01.19	<ol style="list-style-type: none">1. Add U disk recovery function.2. Modify Hold function arithmetic.3. Add the telnet SCPI function; port is 5024 Example: telnet 192.168.0.10 50244. Repair the external trig problem.
2016/3/17	1.01.01.16R2	<ol style="list-style-type: none">1. Improve the UI.2. Fix the bug in the trend chart.3. Modify the number of file systems from 2 to 3 and copy some configuration files to new location .This will reduce the chance of a system crash.4. Need to use transition software to update from old to new version.
2015/10/29	1.01.01.15R2	<ol style="list-style-type: none">1. Fix the bug in thermocouple temperature measurement. Add a sufficient time delay to guarantee the validity of temperature ADC's reading.2. Modify the range of the product ID in update process check.3. Repair SCPI bug and RTD measurement bug.
2015/9/22	1.01.01.15R1	<ol style="list-style-type: none">1. Speed up the refresh rate of UI.2. Modify the storage location of the product model and configuration files to upgrade.3. Add the diode threshold setting function.4. Fixed other miscellaneous problems.
2015/4/01	1.01.01.12R1	<ol style="list-style-type: none">1. Fixed a problem where the LAN MASK setting cannot be saved after reboot.2. Added Gateway setting.3. Fixed other miscellaneous problems.

Update Instructions

1. If the firmware version in your SDM3055 is before 1.01.01.16R2 (not included), Please install the 1.01.01.16R2 firmware first.
2. You can find the firmware as below website:
<http://www.siglentamerica.com/gjjrj-xq.aspx?id=4630&tid=15>