

## Revision History

| Version                   | Revision  |
|---------------------------|---|
| V1.1.1.2.5<br>2021/05/31  | <ol style="list-style-type: none"> <li>Fix: In the custom mode, when save the state, some items are not saved.</li> <li>Fix: Arb mode and pulse mode conflict. Now they can work simultaneously.</li> <li>Fix: In Arb mode, there are some spurs, when On/Off the RF Mode button.</li> <li>Fix: Some problems about LAN setting, VNC</li> </ol>                   |
| V1.1.1.2.4<br>2020/11/12  | <ol style="list-style-type: none"> <li>Fix: The UI was not updated in time when the power meter was pulled out.</li> <li>Fix: GPIB Address can not be changed.</li> <li>Fix: The mouse is hidden under VNC.</li> <li>Fix: Some wrong SCPI commands were executed.</li> <li>Optimize function with OCXO module.</li> <li>Optimize power meter function.</li> </ol> |
| V1.1.1.2.2<br>2020/09/02  | <ol style="list-style-type: none"> <li>Fix: Some power meter related SCPI commands do not work</li> <li>Fix: UI cannot be set without IQ board</li> </ol>   |
| V1.1.1.2.1<br>2020/08/17  | <ol style="list-style-type: none"> <li>Optimize an overshoot signal generated when ALC is off.</li> <li>Changing the offset range of multicarrier.</li> <li>Optimizing the process of multicarrier generation.</li> <li>Add a prompt box when using remote mode.</li> <li>Use new license generation scheme</li> </ol>  |
| V1.1.1.1.9c<br>2020/06/18 | <ol style="list-style-type: none"> <li>Fix: There is a probability that white screen will appear after power on.</li> <li>Fix: AWGN State no reset.</li> <li>The IQ board detection only needs detection once.</li> </ol>   |
| V1.1.1.1.9a<br>2020/5/14  | The first released  |