

Revision History

Date	Version	Revision
2017/4/06	3.01.01.03	<ol style="list-style-type: none">1. Add U disk recovery function.2. Add the update of the calibration data function.3. Fix the bug of a few abnormal DCV measurements when the input terminal is shorted.4. Repair the external trigger problem.5. Add the telnet SCPI function; port is 5024 Example: telnet 192.168.0.10 50246. Some FPGA optimizations.
