SSA3000X Plus Firmware Revision History

Version	Revision
V3.2.2.3.3R1 2020/12/01	New Functionality: • Add EMI filter in SA for EMI option Solved Issues: • Optimize the TG flatness and control procedure • Optimize Help • Fix Correction, .csv file, add peak numbers to 20 in EMI mode • Fix amplitude error in DMA Mode • Fix upgrade failure issue
V3.2.2.3.2 2020/09/09	Solved Issues: • Fix avg power bug in EMI Mode • Fix amplitude bug in AMA Mode • Fix peak search bug in SCPI command
V2.2.1.2.8 2020/06/30	New Functionality: • Update EMI option to a new EMI measurement mode Improvements: • Improve TG output harmonic performance • Update Help file Solved Issues: • Fix ADC overload warning • Fix Ch Power calculation bug in small span
V2.2.1.2.7 2020/05/12	Improvements: • Add Limit mask offset in SA mode • TG Level adjustable in Reflection Meas Solved Issues: • Fixed AM and FM symbol rate error, Lpf coefficient error, in AMA mode • Fixed Filter bandwidth error in DMA mode • Fixed Freq counter error in SA mode • Fixed Harmonic error in SA mode • Help Display error
V2.2.1.2.5	

Version	Revision
2019/11/11	Improvements: • Optimize trace, marker, signal track, TG normalization，Reflection measurement in SA Mode • Optimize web server UI Solved Issues: • Fixed video trigger fail, errors in Harmonic measurement in SA Mode • Fixed spectrum amplitude error, meas error, waveform discontinue in MA Mode • Fixed English help, system message