SSA3000X-R Firmware Revision History

Version	Revision
V3.2.2.3.3R1 2020/12/01	**New Functionality:** • Add EMI filter in SA for EMI option **Solved Issues:** • Optimize the response in RTSA • Optimize the TG flatness and control procedure • Optimize Help • Fix Correction, .csv file, add peak numbers to 20 in EMI mode • Fix ADC overload warning error, and time unit error in Calibration in VNA Mode • Fix amplitude error in DMA Mode • Fix the frequency band downgrade to 3.2GHz on some units • Fix upgrade failure issue
V3.2.2.3.2 2020/09/09	**New Functionality:** • Add VNA and DTF mode • Update EMI option to a new EMI measurement mode **Solved Issues:** • Fix bug in Help File • Fix some ADC overload warning • Fix some PvT and Density marker bugs. • Fix Ch Power calculation bug in small span in SA Mode • Fix amplitude bug in AMA Mode • Fix peak search bug in SCPI command