Revision History

Date	Version	Revision
2021/7/30	6.01.01.22	Compatible with different batches hardware
2019/9/20	6.01.01.21R2	Optimize self-calibration for channels.
2017/4/7	6.01.01.19	1. Repaired bug causing Math error when trace is stopped in dot display mode 2. Fixed 'add measurement' error in Polish language 3. Bug repaired when measuring frequency of 500 Hz, using alternate trigger, and a time base of greater than 1 ms/div
2016/10/20	6.01.01.18	1. Fixed condition where wave trace departs from zero line while there is offset 2. Fixed bug: Sample rate of zoom changed after STOP in dot display mode 3. Fixed bug: All measurements on, select source on a disable channel. Reboot the Scope, then the software hangs on the boot screen 4. Adjusted keyboard scan method to optimize recognizing keyboard value 5. Modified BMP from 24bit to 16bit while save/get BMP form Scope
2015/11/30	6.01.01.08	The first formal release

Compatibility between Versions

Source Version	Object Version	Compatibility

Update instructions

Before updating the ADS file, the ADS file need to be renamed and ensured that its name is less than 9 letters.