

Revision History

Date	Version	Revision
2023/11/28	1.02.01.02.02R3	1. Improved LED blinks Notes: <ul style="list-style-type: none"> A. V2.0 hardware version of SPD3303C do not support rolling back to the previous firmware version B. V1.0 hardware version of SPD3303C do not support upgrading to this version C. Press and hold the "NO.1~5" button for 2 seconds, after releasing it, it will display H2.0, which is the V2.0 version hardware



2022/09/27	1.02.01.02.02	1. This firmware version only supports V2.0 hardware version of SPD3303C Notes: <ul style="list-style-type: none"> A. V2.0 hardware version of SPD3303C do not support rolling back to the previous firmware version B. V1.0 hardware version of SPD3303C do not support upgrading to this version C. Press and hold the "NO.1~5" button for 2 seconds, after releasing it, it will display H2.0, which is the V2.0 version hardware
------------	---------------	---



2. Need to use P20 version EasyPower to upgrade this firmware

Date	Version	Revision
2022/6/8	1.02.01.01.03R10	<ol style="list-style-type: none">1. Add the OCP function (Long push the current button ('A') get into or exit OCP function)2. Some improvements about the USB's stability.3. Compatible new ADC
2020/10/15	1.02.01.01.03R6	<ol style="list-style-type: none">1. The buzzer abnormally sounds when the set value overranges2. Changed the limit of series voltage to 60V3. Fixed a bug of recall function.