

Revision History

Date	Version	Revision
2023/3/23	1.1.1.22R1	1. Modify the BUG of the fan false trigger protection function;
2022/9/8	1.1.1.22	1. Modify the EEROM model software matching upgrade;
2021/5/20	1.1.1.21R2	1. Fix bug: DHCP turn to be ON state after send *RST command. 2. Some units will crash after run for some time.
2020/1/14	1.1.1.21	1. The software version adds socket functionality and support for EasySDL.
2019/4/16	1.1.1.19R1	1. The first software version

Compatibility between Versions

Source Version	Object Version	Compatibility
1.1.1.19R1		Yes
1.1.1.21		Yes
1.1.1.21R2		Yes
1.1.1.22		Yes
1.1.1.22R1		Yes

Update instructions

- ◆ Very important!
After the upgrade is complete, restart the machine.