

## **Revision History**

Date	Version	Revision
2017/4/7	6.02.01.08	<ol> <li>Repaired bug causing Math error when trace is stopped in dot display mode</li> </ol>
		2. Fixed 'add measurement' error in Polish language
		3. Bug repaired when measuring frequency of 500 Hz, using
		alternate trigger, and a time base of greater than 1
		ms/div
2016/10/20	6.02.01.07	Fixed condition where wave trace departs from zero line while there is offset
		<ol><li>Fixed condition where wave trace departs from zero line while there is offset</li></ol>
		<ol><li>Fixed bug: All measurements on, select source on a disable channel. Reboot the Scope, then the software hangs on the boot screen</li></ol>
		<ol> <li>Adjusted keyboard scan method to optimize recognizing keyboard value</li> </ol>
		<ol><li>Modified BMP from 24bit to 16bit while save/get BMP form Scope</li></ol>
		6. Fixed the bug: Wave trace disappear after STOP in scan mode
2016/5/10	6.02.01.02	The first formal release



## **Compatibility between Versions**

Source	Object	Compatibility
Version	Version	

## **Update instructions**

Before updating the ADS file, the ADS file need to be renamed and ensured that its name contains less than 9 letters