

## Revise History

Date	Version	Revision
8/30/2018	1.08.01.13R6	Fixed the incorrect sweep direction bug (2018/05/23-115276)
3/21/2018	1.08.01.13R5	<b>It is strongly recommended to update to the latest release because in some previous release exists some serious bug which could cause the generator never startup</b> <ol style="list-style-type: none"><li>1. Supported system recovery from the U-disk</li><li>2. Supported Rev.C hardware with Over Voltage Protection</li></ol>
6/7/2016	1.08.01.12R2	Fixed several bugs <ol style="list-style-type: none"><li>a) A bug in P12R1 which could cause the update to fail</li><li>b) Some typo in English help system</li></ol>
3/7/2016	1.08.01.12R1	Fixed several bugs <ol style="list-style-type: none"><li>a) A bug in file system could cause the generator never startup</li><li>b) Can not wake up from screen saver from time to time</li></ol>
11/9/2015	1.08.01.11	<ol style="list-style-type: none"><li>1. Re-open the self-calibration function</li><li>2. Fixed a bug which may cause the generator can not startup</li><li>3. Fixed several other bugs</li></ol>