


## Revision History

Date	Version	Revision
2022/09/27	1.02.01.02.02	<p>1. This firmware version only supports V2.0 hardware version of SPD3303C</p> <p><b>Notes:</b></p> <p>A. V2.0 hardware version of SPD3303C do not support rolling back to the previous firmware version</p> <p>B. V1.0 hardware version of SPD3303C do not support upgrading to this version</p> <p>C. Press and hold the "NO.1~5" button for 2 seconds, after releasing it, it will display H2.0, which is the V2.0 version hardware</p>
		
		<p>2. Need to use P20 version EasyPower to upgrade this firmware</p>
2022/6/8	1.02.01.01.03R10	<p>1. Add the OCP function (Long push the current button ('A') get into or exit OCP function)</p> <p>2. Some improvements about the USB's stability.</p> <p>3. Compatible new ADC</p>
2020/10/15	1.02.01.01.03R6	<p>1. The buzzer abnormally sounds when the set value overranges</p> <p>2. Changed the limit of series voltage to 60V</p> <p>3. Fixed a bug of recall function.</p>