

Revise History

Date	Version	Revision
2017/12/08	1.01.01.02.05	<ol style="list-style-type: none">1. Add Socket interface support.2. Repaired bug in the LAN interface function3. Restrict the total output voltage in the serial mode not to exceed 60V in order to satisfy the requirements of TUV.
2016/12/02	1.01.01.02.03	<ol style="list-style-type: none">1. Add CH3' s on/off control by SCPI command.2. Fix the bug of the update process of DAC.
2016/1/04	1.01.02.02R2	<ol style="list-style-type: none">1. Modify the UI.2. Fix some bugs of remote control..
	1.01.02.03	<ol style="list-style-type: none">1. Add the CH3' s SCPI control command.2. Fixed a design bug about voltage setup.

Version compatibility

Source Version	Object Version	Compatibility
-------------------	-------------------	---------------

Update instructions

- 1、 To upgrade you firmware, you should download EasyPower(please download it on <http://www.siglent.com/gjjrj-xq.aspx?id=1632&tid=14>) to your computer. And then you can upgrade your firmware via USBTMC. Please refer to the specific steps to upgrade on the SPD3303X Firmware Update Instructions.