

SHA860A Firmware Revision History

Version	Revision
Software: 1.6R8 Uboot-OS: 3.8.10 2025/7/24	<ul style="list-style-type: none"> ● New ATT and RefLevel linkage solution. ● Limit function optimization. ● Other function optimizations and bug fixes
Software: 1.5R1 Uboot-OS: 3.8.10 1/7/2024	<p>New Functionality:</p> <ul style="list-style-type: none"> ● Add EMI Mode. ● Add GNSS altitude units, time zones. <p>Solved Issues:</p> <ul style="list-style-type: none"> ● Solve the issues of rtss screenshot, reset, color parameter, trace detector type. ● Solve the issues of Pulse's RBW, Preset, trigger negative delay, etc. ● Optimize daylight mode, buzzer and other settings. ● Solve multiple issues of NR/LTE and their record playback.
Software: 1.3R3 Uboot-OS: 3.8.10 6/12/2024	<p>New Functionality:</p> <ul style="list-style-type: none"> ● Add timing access in GNSS. ● Add the online map. ● Add field strength measurement in GPSA mode. ● Add Gate in CHPower. ● Add PvT measurement, Gate and Trigger GPS-1pps, in NR mode. ● Add IQA acquisition from I=Q=4B to 2B. <p>Solved Issues:</p> <ul style="list-style-type: none"> ● Optimize typical power consumption reduction. ● Solve record playback issues. ● Solve uneven VNA response. ● Solve RTSA marker and other issues. ● Solve NR, LTE mode synchronization issues. ● Solve the problem of temperature complement anomaly.
V1.2R1 10/18/2023	<p>The first time introduced.</p> <p>Features in Data Sheet EN01A.</p>