

Revise History

Date	Version	Revision
7/16/2019	1.08.01.13R9	Fixed the abnormal display issue during start-up on some units with previous releases. It is not necessary to update to this version if the unit has no such a problem.
8/30/2018	1.08.01.13R6	Fixed the incorrect sweep direction bug (2018/05/23-115276)
3/21/2018	1.08.01.13R5	It is strongly recommended to update to the latest release because in some previous release exists some serious bug which could cause the generator never startup <ol style="list-style-type: none">1. Supported system recovery from the U-disk2. Supported Rev.C hardware with Over Voltage Protection
6/7/2016	1.08.01.12R2	Fixed several bugs <ol style="list-style-type: none">a) A bug in P12R1 which could cause the update to failb) Some typo in English help system
3/7/2016	1.08.01.12R1	Fixed several bugs <ol style="list-style-type: none">a) A bug in file system could cause the generator never startupb) Can not wake up from screen saver from time to time
11/9/2015	1.08.01.11	<ol style="list-style-type: none">1. Re-open the self-calibration function2. Fixed a bug which may cause the generator can not startup3. Fixed several other bugs