

Revise History

Date	Version	Revision
12/3/2020	1.08.01.15	<ol style="list-style-type: none"> Supported to automatically enable the output after power-on: Utility Output Setup Power on State Compatible with Rev.E hardware
7/16/2019	1.08.01.13R9	Fixed the abnormal display issue during start-up on some units with previous releases. It is not necessary to update to this version if the unit has no such a problem.
8/30/2018	1.08.01.13R6	Fixed the incorrect sweep direction bug (2018/05/23-115276)
3/21/2018	1.08.01.13R5	<p>It is strongly recommended to update to the latest release because in some previous release exists some serious bug which could cause the generator never startup</p> <ol style="list-style-type: none"> Supported system recovery from the U-disk Supported Rev.C hardware with Over Voltage Protection
6/7/2016	1.08.01.12R2	Fixed several bugs <ol style="list-style-type: none"> A bug in P12R1 which could cause the update to fail Some typo in English help system
3/7/2016	1.08.01.12R1	Fixed several bugs <ol style="list-style-type: none"> A bug in file system could cause the generator never startup Can not wake up from screen saver from time to time
11/9/2015	1.08.01.11	<ol style="list-style-type: none"> Re-open the self-calibration function Fixed a bug which may cause the generator can not startup Fixed several other bugs