

## Revision History

Date	Version	Revision
2021/2/5	5.01.01.06R1	<ol style="list-style-type: none"><li>1. Fixed some unit faults in 06 version</li><li>2. Fixed some bugs about communication with EasyDMM.</li></ol>
2021/1/8	5.01.01.06	<ol style="list-style-type: none"><li>1. Fixed some crash fault about U disk Save&amp;Recall.</li><li>2. Fixed some bugs about “acquire” function.</li><li>3. Improve the trend display function.</li><li>4. Update the software platform code.</li></ol>
2019/4/23	5.01.01.05	<ol style="list-style-type: none"><li>1. Change the size of text in dual display mode.</li><li>2. Added customer defined time base in the trend diagram.</li><li>3. Enhanced the volume of buzzer.</li><li>4. Bug fix: The screen saving setup was lost after power cycle/reboot.</li><li>5. Moved CSV file save function from the utility page to the acquire page.</li><li>6. Added recording measurement data to external U disk.</li></ol>
2017/6/06	5.01.01.03	<ol style="list-style-type: none"><li>1. Add U disk recovery function.</li><li>2. Modify Hold function arithmetic.</li><li>3. Add the telnet SCPI function; port is 5024</li><li>4. Example: telnet 192.168.0.10 5024</li></ol>